


Current Measurement Transformer LL3013

Current measurement transformer, 300A : 1A

Connection schematic:



Usage, 300A to 1A.

Out+ 1

Out- 3

Connect 2 - 4