

Test Results Tube ECC802S-1L

Test Method Auto Bias

Item		Spec	Result 1	Result 2
Plate Volts	Ep vdc	250	250	250
DC Plate Current	Ip mAdc	9.5	9.5	9.5
AC Plate Current	Ip mAac	~	0.26	0.24
Screen Volts	G2 vdc	0	0	0
Screen Current	IG2 mA	0	0	0
Bias Volts	G1 vdc	9	9.5	9.2
Test Signal Volts	RMS	~	0.1	0.1
Mutual Conductance	uMhos	2100	2600	2400
Grid #1 Leakage	uA	0	0.02	0.02
H/K Leakage	mA	0	0	0
Plate Resistance	RP ohms	~	7.6K	7.9K
Tube Gain	Mu	~	19.7	18.9
Heater	eF vdc	12.6	12.6	12.6
Heater Run Time	Sec		152	177
Timestamp		29.03.2022	11:47:03	

Tube# 4 JACMUSIC Horber Steige 25 72172 Sulz * Germany
---